IN GROUND POOL BONDING

ALL METAL PARTS WITHIN 5' OF THE POOL MUST BE BONDED TO THE COPPER WIRE CIRCUIT TRAVELLING AROUND THE POOL.



